

5 Railroad Street . P.O. Box 359

Newmarket, NH 03857 Phone: (603) 659-4979

Email: mjs@mjs-engineering.com

RECEIVED
Town of Durham

OCT 28 2015

TEST PIT LOGS

Planning, Assessing and Zoning

PROPERTY OWNER: PROPERTY ADDRESS:

LOCATION:

Harmony Homes by the Bay

W. Arthur Grant Circle, Durham, NH 03824

Tax Map #11 Lots #27-1 thru 27-7

DATE TEST PITS PERFORMED:

TEST PITS LOGGED BY: TEST PITS WITNESSED BY:

TEST PITS DUG BY:

08/27/15

Michael J. Sievert

Designer #

773

G BY: Coulstring Construction, LLC-small backhoe

Test Pit #1

Closest to Pump Station

0-6"

Fine sandy loam

6-18"

Very fine silt loam, blocky, friable

18-44"

Very fine silty clay loam, blocky, firm

ESHW 12"

Test Pit #2

0-6"

Loam, topsoil

6-12"

Fine sandy loam, friable, granular

12-33"

Very fine silty clay loam, blocky, firm

ESHW 15"

Test Pit #3

Front Right Building Corner

0-6"

Topsoil

6-24"

Fine sandy loam, granular, friable

24-48"

Loamy fine sand, granular, friable More rocky, large boulder @ 48"

ESHW 20"

Test Pit #4

Interior Courtyard Building #1

0-6"

Topsoil (10yr, 4/3)

6-15"

Very fine sandy loam, granular, friable (2.5y, 5/3)

15-60"

Silty clay loam, blocky, firm, (5y, 5/2)

ESHW 14"

Test Pit #5 0-6" 6-12" 12-48+"	Interior Courtyard Building #2 Topsoil Very fine silt loam, blocky, friable Very fine silty clay loam, blocky, firm ESHW 14"
Test Pit #6 0-6" 6-14" 14-48"	Lower Level Building #2 Topsoil Fine sandy loam, granular, friable Very fine silty clay loam, blocky, firm ESHW 15"
Test Pit #7 0-6" 6-14" 14-25" 25-54"	Upper Left Building #2 Topsoil Fine sandy loam, granular, loose (2.5y, 5/4) Fine silty loam, granular, friable (2.5y, 5/4) Silty clay loam, blocky, firm

ESHW 20"