From: John Powers

Sent: Monday, December 10, 2018 1:59 PM

To: Michael Behrendt

Subject: RE: Edgewood Road #48 - Fire Review

Here are my notes:

III. <u>48 Edgewood Road – 2-Lot Subdivision</u>. Subdivision of 2.16 acre lot. Geoffrey Lombard and Jane Miller, property owners. Paul Dobberstein, Ambit Engineering, surveyor. Map 1, Lot 16-2. Residence A District.

FD Notes: The FD believes it is important to note that, depending on where the future proposed building and foundation may be located, certain building / fire code requirements may be applied if the proposed building is within close proximity of adjacent buildings. For example, if a proposed building is within thirty feet of the existing adjacent home, the exterior wall on the proposed building facing the existing home may need to be fire-rated, with restrictions on how many openings it may have such as doors and windows. Otherwise, the FD has no other immediate concerns

Closest Hydrants:

Lat: 43.14750° N Lon: 70.92674° W

AND

Lat: 43.14652° N **Lon:** 70.92602° W

MAP IS ATTACHED

John T. Powers, Deputy Chief Durham Fire Department (603) 862-1426



