

---

**SITE PHOTOS (Taken 2-28-2022)**



Location of the proposed driveway looking up station from approximately Station 3+50. For reference you will see the stone wall and the large tree to the left shown with orange surveyor's tape. This tree is near the property corner shown on the plan. Wetland is located to the right.



This photo is looking back in the opposite Direction. Notice the large tree on the right this Time. The wetland is to the left.



This photo shows the wetland while standing on the proposed location of the driveway location. There is a wetland flag tied to a small shrub just past the first log on the ground.



This photo shows the wetland to the right While standing on the proposed driveway Location.